# DATA SHEET

Three Phase Induction Motor - Squirrel Cage

:

#### Customer

Product line		: Prei	mium Effici	iency Three-P		Product code : Catalog # :	13575373 00136ET3H	IW56C-S
Frame Output Poles Frequency Rated voltage Rated current L. R. Amperes LRC No load current Rated speed Slip Rated torque Locked rotor toro Breakdown torqu Insulation class Service factor Moment of inerti	ue	: 2 : 60 H : 575 : 1.20 : 8.8) : 0.63 : 343 : 4.58 : 1.53 : 360 : 380 : 5 F : 1.15	P (0.75 kW Hz V A A A (Code M) 38 A 5 rpm 3 % 3 ft.lb % %		Temper Duty cy Ambier Altitude Protect Cooling Mountin Rotatio Noise k Starting	nt temperature ion degree g method ng n <sup>1</sup>	: 18s (cold) : 80 K : Cont.(S1) : -20°C to + : 1000 m.a. : IP55 : IC411 - TF : F-1 : Both (CW : 65.0 dB(A : Direct On : 21.9 lb	+40°C .s.l. EFC and CCW)
Output	25%	50%	75%	100%	Foundatio	on loads		
Efficiency (%)	72.4	74.0	77.0	78.5	Max. trac		: 46 lb	
Power Factor	0.38	0.63	0.75	0.80	Max. com	pression	: 68 lb	
Bearing type Sealing Lubrication interval Lubricant amount Lubricant type		Drive end   : 6203 ZZ   : V'Ring   : -   : -   : -   : Mol			<u>Non drive end</u> 6202 ZZ Without Bearing Seal - - bil Polyrex EM			
Notes				Мо	bil Polyrex	EM		
Votes				Mo	bil Polyrex	EM		
Notes Fhis revision repl nust be eliminate 1) Looking the m 2) Measured at 3) Approximate manufacturing pr 4) At 100% of fu Rev.	ed. notor from 1m and wi weight sub rocess.	the shaft e th toleranc oject to cha	end. e of +3dB( anges after	one, which A).	These at	EM re average values upply, subject to th Performed		
This revision repl nust be eliminate 1) Looking the m 2) Measured at 3) Approximate nanufacturing pr 4) At 100% of fu	ed. notor from 1m and wi weight sub rocess.	the shaft e th toleranc oject to cha	end. e of +3dB(	one, which A).	These an power su	re average values	e tolerances stipu	lated in NEMA
This revision repl nust be eliminate 1) Looking the m 2) Measured at 3) Approximate nanufacturing pr 4) At 100% of fu Rev.	ed. notor from 1m and wi weight sub rocess.	the shaft e th toleranc oject to cha	end. e of +3dB( anges after	one, which A).	These an power su	re average values	e tolerances stipu	lated in NEMA
This revision repl nust be eliminate 1) Looking the m 2) Measured at 3) Approximate nanufacturing pr 4) At 100% of fu	ed. notor from 1m and wi weight sub rocess.	the shaft e th toleranc oject to cha	end. e of +3dB( anges after	one, which A).	These an power su	re average values	e tolerances stipu	lated in NEMA


Шеq

This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.

1/5

11/04/2022

Date




Subject to change without notice

## LOAD PERFORMANCE CURVE


Three Phase Induction Motor - Squirrel Cage

:

#### Customer



This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.




This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.

### VFD OPERATION CURVE


:

Three Phase Induction Motor - Squirrel Cage

#### Customer



This document is exclusive property of WEG S/A. Reprinting is not allowed without written authorization of WEG S/A.



WEG's property. Forbidden reproduction without previous authorization.








MAT: 13575373

W01.TE0IC0X0X MODEL 00136ET3HW56C-S

3APR2022 B/N:

For 60Hz: Class I, Zone 2, IIC Class I, DIV.2, Gr. A,B,C,D - T3 DIV 2 Inverter Duty (SF1.00)

T3AFX2022 B/N: C12:1/1/1   FR W56C HP 1.0 C12:1/1/1   FR W56C KW 0.75 DUT C00.1 F   DUT T000m.as.l A 1.26 A 1.26 A   NIS CLF AT 60K FE 255 A 1.38 A 1.36   A 1.20 NIS CLF AT 60K FES 5 1.15 A 1.36   A 0.50 MES F 1.38 A 1.15 A 1.15   AMB 40°C DES F P 0.80 A



牌

NTERCHANGE ANY TWO LINE WIRES TO REVERSE THE ROTATION



NARNING: Motor must be grounded in accordance with local chocks. Disconnect power source before servicing unit. ind national electrical codes to prevent serious electrical

choc électrique grave. Déconnectez l'alimentation avant l'entrefien de la machine conformément aux codes électriques locaux et nationaux afin d'éviter tout AVERTISSEMENT: Le moteur doit être mis à la terre

